
Table of Contents

Executive Summary	1
Warranty Inspection Process.....	1
Warranty Inspection Results.....	2
1.0 Warranty Inspection Process.....	3
2.0 Rights-of-Entry, Public Notification, and Permits.....	5
3.0 Weather Conditions during Warranty Inspection	6
4.0 Pilot Project Warranty Results.....	6
4.1 Warranty Results by Pilot Project.....	7
4.2 Warranty Results by Sewer System Component	10
4.2.1 Sewer Mains.....	10
4.2.2 Laterals and Side Sewers.....	18
4.2.3 Cleanouts.....	23
4.2.4 Manholes	23
5.0 CCTV Standards	24
6.0 Warranty Inspection Costs	25
7.0 Lessons Learned.....	26

List of Tables

Table 1 – Constructed Rehabilitation Techniques and Products	4
Table 2 - Warranty Inspection Costs.....	25

List of Figures

Figure 1 – Homeowner installation of CIP liner in lateral	9
Figure 2 – Irrigation pipe bored through a side sewer in Skyway	10
Figure 3 – Leak at the bottom of a welded saddle connection in Skyway	12
Figure 4 – Non-HDPE coupling used during pipe busting	12
Figure 5 – Black HDPE pipe in Skyway	13
Figure 6 – Gray HDPE pipe in Auburn.....	13
Figure 7 – Defective CIPP in 12-inch-diameter sewer main in Brier.....	15
Figure 8 – Active leak through CIP liner in Mercer Island.....	16
Figure 9 – Curled edge on the upstream edge of a CIPP spot repair in Mercer Island	17
Figure 10 – Photo of pipe in Lake Forest Park	18
Figure 11 – Photo of a Mercer Island TOP HAT™	19
Figure 12 – Photo of a Mercer Island TOP HAT™	20
Figure 13 – TOP HAT™ in Lake Forest Park that has no defects	20
Figure 14 – Photo of a Mercer Island TOP HAT™	21
Figure 15 – Photo of T-Liner® from Redmond.....	22
Figure 16 – Photo of T-Liner® from Redmond.....	22