Clamshell Dredging Operations



Loading the Barge

Offloading/Rehandling Facility



Stockpiling Sediment at the Offloading/Rehandling Facility

Habitat Mix Placed Over the Existing Rip Rap.

Placing rip rap.

Placing rip rap.