

Errata

Errata

**FINAL
SUPPLEMENTAL
ENVIRONMENTAL
IMPACT STATEMENT**

**Brightwater
Regional Wastewater
Treatment System**

Errata

References

The following references, listed according to where they were given in the Supplemental Draft EIS, have been revised to correct errors or to supply additional information to aid in locating the documents. Some references are repeated if they appeared in more than one place in the document.

Chapter 2

Aspect Consulting. 2005. North Mitigation Area trench boring investigation summary—Brightwater Treatment Plant seismicity investigation. Memorandum to CH2M HILL dated March 9.

Atwater, B.F., and Hemphill-Haley, E. 1997. Recurrence intervals for great earthquakes of the past 3,500 years at Northeastern Willapa Bay, Washington. U.S. Geological Survey Professional paper 1576.

Chapter 4

Blakely, R.J., Wells, R.E., Weaver, C.S., and Johnson, S.Y. 2002. Location, structure, and seismicity of the Seattle Fault Zone, Washington: Evidence from aeromagnetic anomalies, geologic mapping, and seismic-reflection data. *Geological Society of America Bulletin*, 114 (2), 169-177.

Earthquake Engineering Research Institute (EERI). 1990. Earthquake Spectra. Supplement to Volume 6. *Loma Prieta Earthquake Reconnaissance Report*. Lee Benuska, Editor. May 1990.

Earthquake Engineering Research Institute (EERI). 1995. Chapter 4, Lifelines (pp. 143-176). Supplement C to Volume 11. Northridge Earthquake of January 17, 1994 reconnaissance report, Volume 1. Publication 95-03. John F. Hall, Editor. *Earthquake Spectra*. April 1995.

National Center for Earthquake Engineering Research (NCEER). 1995. Section 8, Water and wastewater (pp. 8-1–8-56). *The Hanshin-Awaji Earthquake of January 17, 1995, performance of lifelines*. Edited by M. Shinozuka. Buffalo, New York: NCEER.

Chapter 5

EPA. 1993. *Wildlife Exposure factors handbook* (vol. 1). EPA 600/R-93/187a. Washington, DC: U.S. Environmental Protection Agency, Office of Research and Development.

Appendix A

CH2M HILL. 2004. *Preliminary design geotechnical interpretive report, Route 9 site, Proposed Brightwater Wastewater Treatment Plant*. Unpublished consultant's report to King County Wastewater Division, Washington.

CH2M HILL. 2005. *Final design geotechnical recommendations report, Brightwater Regional Wastewater Treatment Plant*. Unpublished consultant's report to King County Wastewater Division, Washington.

Wells, D.W., and Coppersmith, K.J. 1994. New empirical relationships among magnitude, rupture length, rupture width, rupture area, and surface displacement. *Bulletin of the Seismological Society of America*, 84, 974-1002.

Appendix B

AMEC Earth & Environmental, Inc. 2004. Draft report: surface-fault-rupture hazard evaluation, Brightwater Wastewater Treatment Plant site, Snohomish County, Washington. Report by AMEC Earth & Environmental, Anaheim, CA, 4-212-102100, for Bob Peterson, King County Wastewater Treatment Division, Seattle, WA. January.

Blakely, R.J., Wells, R.E., Weaver, C.S., and Johnson, S.Y. 2002. Location, structure, and seismicity of the Seattle Fault, Washington: Evidence from aeromagnetic anomalies, geologic mapping, and seismic-reflection data. *Geological Society of America Bulletin*, 114 (2), 169-177.

Byrne, D., Davies, D., and Sykes, L. 1988. Loci and maximum size of thrust earthquakes and the mechanics of the shallow region of subduction zones. *Tectonics*, 7 (4), 833-857.

Crouse, C. 1991. Ground motion attenuation equations for earthquakes on the Cascadia subduction zone. *Earthquake Spectra*, 7 (2), 201-236.

Hyndman, R.D., and Wang, K. 1993. Thermal constraints on the zone of major thrust earthquake failure: The Cascadia Subduction Zone. *Journal of Geophysical Research*, 98 (B2), 2039-2060.

Hyndman, R.D., and Wang, K. 1995. The rupture zone of Cascadia great earthquakes from current deformation and the thermal regime. *Journal of Geophysical Research*, 100 (B11), 22,133 -22,154.

Wells, R.E., and Johnson, S.Y. 2001. Deformation of Western Washington resulting from northward migration of the Cascadia Forearc. *Seismological Research Letters*, 72 (2), 237-238.

Appendix B-A

Atwater, B.F., and Moore, A.L. 1992. A tsunami about 1000 years ago in Puget Sound, Washington. *Science*, 258, (5088), 1614-1617.

Blakely, R.J., Wells, R.E., Weaver, C.S., and Johnson, S.Y. 2002. Location, structure, and seismicity of the Seattle Fault Zone, Washington: Evidence from aeromagnetic anomalies, geologic mapping, and seismic-reflection data. *Geological Society of America Bulletin*, 114 (2), 169-177.

Pratt, T.L., Johnson, S.Y., Potter, C.J., and others. 1997. Seismic-reflection images beneath Puget Sound, Western Washington State. *Journal of Geophysical Research*, 102 (B12), 27,469-27,489.

Appendix B-B

AMEC Earth & Environmental, Inc. 2004. Draft report: surface-fault-rupture hazard evaluation, Brightwater Wastewater Treatment Plant site, Snohomish County, Washington. Report by AMEC Earth & Environmental, Anaheim, CA, 4-212-102100, for Bob Peterson, King County Wastewater Treatment Division, Seattle, WA. January.

Appendix D

EPA. 1993. *Wildlife Exposure factors handbook* (vol. 1). EPA 600/R-93/187a. Washington, DC: U.S. Environmental Protection Agency, Office of Research and Development.

Appendix E

Monzaki, Yosh. 2004. Personal communication. Stormwater Engineer, City of Woodinville, Washington. November 15, 2004.

Figures

Two street names were incorrectly labeled in figures in the Draft Supplemental EIS. The streets were labeled as 228th Street SW and 223rd Place SW. The correct names are 228th Street SE and 223rd Place SE.

The following figures were mislabeled:

Figure 1-3

Figure 1-4

Figure 2-3

Figure 3-2

Figure 3-4

Figure 5-4

Figure SW-3 (Appendix E)

Technical Appendices

Appendix D

Page 8, “Ecological Water Quality Screen for Chemicals,” second sentence: delete “chronic.”

Page 9, second paragraph, second sentence, change “95% lower confidence limit” to “5% lower confidence limit.”

Page 9, third paragraph, fourth sentence, change “effects aquatic” to “effects to aquatic.”